




K · PIT



NSR50/80/mini Series

**NSR50 / 80 / mini SERIES!
RADIATOR HOSE RELEASED!**



PRINTED "KITACO"

REPLACEMENT SILICONE RADIATOR HOSE.

If coolant leakage or seepage occurs due to hose deterioration or cracking, must be replaced with new one.



▲ NSR mini
Vol.14-2

▲ A

D ▶

▼ C

NSR80
Vol.14-2

B ▶



RADIATOR HOSE (A)



RADIATOR ⇄ FILLER NECK

APPLICATION NSR50 (AC10)、NSR80 (HC06)

NOTES ● REPLACEMENT ● SILICONE ● BLACK
● GENUINE PARTS NO. : 19125-GT4-000

※Genuine hose clamp not usable. 2 stainless steel bands are required for installation.
(Refer to Vol. 14-2 below)

CODE	PRICE	JAN CODE
70-991-10411	¥ 1,700	4 990852 114832

RADIATOR HOSE (B)



CYLINDER ⇄ R. CRANK CASE COVER

APPLICATION NSR50 (AC10)、NS-1 (AC12)、NS50F (AC08)、MBX50/F (AC03/AC08)、CRM50 (AD10/AD13)、MTX50R (AD06)、CRM80 (HD11/HD12)、MBX80 INTEGRA (HC04)、MTX50R (HD08)、NSR mini

NOTES ● REPLACEMENT ● SILICONE ● BLACK ● GENUINE PARTS NO. : 19501-GT4-000 / 19501-GE2-000 / 19502-GE2-000

※Genuine hose clamp not usable. 2 stainless steel bands are required for installation.
(Refer to Vol. 14-2 below)

CODE	PRICE	JAN CODE
70-991-10412	¥ 2,300	4 990852 114849

RADIATOR HOSE (C)



FILLER NECK ⇄ CYLINDER HEAD

APPLICATION NSR50 (AC10)、NSR80 (HC06)、NSR mini

NOTES ● REPLACEMENT ● SILICONE ● BLACK
● GENUINE PARTS NO. : 19502-GT4-000

※Genuine hose clamp not usable. 2 stainless steel bands are required for installation.
(Refer to Vol. 14-2 below)

CODE	PRICE	JAN CODE
70-991-10413	¥ 2,200	4 990852 114856

RADIATOR HOSE (D)



R. CRANK CASE COVER ⇄ RADIATOR

APPLICATION NSR50 (AC10)、NSR80 (HC06)、NSR mini

NOTES ● REPLACEMENT ● SILICONE ● BLACK
● GENUINE PARTS NO. : 19503-GT5-000

※Genuine hose clamp not usable. 2 stainless steel bands are required for installation.
(Refer to Vol. 14-2 below)

CODE	PRICE	JAN CODE
70-991-10414	¥ 2,200	4 990852 114863



Vol.14-2

